










# Matrix Overview WS Series



Wind	Temperature Relative humidity Air pressure	Temperature Relative humidity Air pressure Precipitation	Temperature Relative humidity Air pressure Radiation
------	--	---	---

## Lufft WS Sensors: The Reference

								
Ventus		WS3000				WS3100		

## Lufft WS Sensors: WMO-Standard

								
WS200	V200	WS300		WS400		WS310	WS301/303	

## Lufft WS Sensors: Meteo-Smart

								
			WS401		WS302	WS304		

# THE REFERENCE WMO-STANDARD METEO-SMART

Temperature  
Relative  
humidity  
Wind speed  
and direction

Temperature  
Relative humidity  
Air pressure  
Wind speed  
Wind direction  
Radiation

Temperature  
Relative humidity  
Wind speed  
Wind direction  
Precipitation

Temperature  
Relative  
humidity  
Wind speed  
Wind direction  
Precipitation  
Radiation



WS510



WS800



WS500



WS501



WS503



WS600



WS700



WS502



WS504



WS601